Second Island

Second Island - Tree Report Actions

T026	Remove
T027	Lateral reduction by at least 2m to ensure sufficient clearance from the footpath to allow for future
	growth over the next few years





View of T026

Remove



View of T027

Lateral reduction by at least 2m to ensure sufficient clearance from the footpath to allow for future growth over the next few years

BODMIN HILL

Bodmin Hill - Tree Report Actions

T028	Prune to provide sufficient clearance from the adjacent overhead services and streetlight. Crown reduction to reduce height by up to 1.5m and the spread from 1.5 - 2.5m depending on available pruning points and to provide a min of 1m clearance from overhead services and streetlight. Pruning wounds are to be below 50mm in diameter when measured across the cut surface
T029	Northeastern lower branches laterally reduced to provide a min of 1.5m lateral clearance between branch tips and adjacent overhead services
T030	Remove basal epicormic growth
T031	Remove basal epicormic growth





View of T028

Prune to provide sufficient clearance from the adjacent overhead services and streetlight.

Crown reduction to reduce height by up to 1.5m and the spread from 1.5 - 2.5m depending on available pruning points and to provide a min of 1m clearance from overhead services and streetlight.

Pruning wounds are to be below 50mm in diameter when



View of T029

Northeastern lower branches laterally reduced to provide a min of 1.5m lateral clearance between branch tips and adjacent overhead services



View of T030

Remove basal epicormic growth



View of T031

Remove basal epicormic growth

Cemetery and Allotments

Cemetery and Allotments

T032 Selective lateral reduction away from adjacent building to provide a min of 1m clearance between branch tips and adjacent cemetery building





View of T032

Selective lateral reduction away from adjacent building to provide a min of 1m clearance between branch tips and adjacent cemetery building